

Oberlin Bend May 12, 2015







Road edge damage from mid
winter avalanches – The Slopes
5/12/2015



Point release slide on Mt Oberlin
and above Oberlin Bend
May 12, 2015

